



A





Turn this bolt to the left with a hexagonal wrench and hold the element support on the front of the machine.

B



Turn this bolt to the left with a hexagonal wrench and hold the element support on the front of the machine.




E

This picture shows you how the two (element support, heating element) meet eachother.



F


This picture shows you how it should look if everything is correctly mounted in the machine.



There should always be a little space between.

G


This picture shows you how the nipple and the sloth belong in each other.



These should meet together

H

This picture shows you how it should look if the nipple and the sloth are mounted in the machine.



There should always be a little space between.